
NTV-DOC272 JH (rev 1.4) 09/12/19



BENTLEY-HUR

NTV-KIT783

Select Bentley head-unit replacement kit



DO NOT ATTEMPT TO FIT THE BENTLEY-HUR UNTIL YOU HAVE READ THE INSTALL MANUAL

The BENTLEY-HUR allows you to install any (double din) after market head unit into Bentley GT / GTC / SPUR 2004-2011. Everything you need to install the after market head unit is contained within this kit.



Main Unit



Audio Harness



Antenna Booster

Kit Content



L-Brackets



Acc power harness



GPS cable



*NOTE: For U.S. installations, cut off black plug on this harness and hardwire to radio (if still present)

Power harness*



Mounting Screws



Audio isolator

Tools required



Torx T20



Trim Remover



Removal Keys A



Removal Keys B




Right angle pick

IMPORTANT NOTE:

The original Navigation, CD changer and the Telephone kit must be disconnected (details shown in the following pages).

REAR OF MAIN UNIT



AUDIO / SW CONTROLS (1)

PIN	COLOR	FUNCTION
1	WHITE 3.5mm JACK	STEERING WHEEL (Signal)
2	BLACK 3.5mm JACK	STEERING WHEEL (Shield)
4	WHITE	FRONT RCA AUDIO SIGNAL (L) (connect to RCA out on radio)
5	RED	FRONT RCA AUDIO SIGNAL (R) (connect to RCA out on radio)
6	BLUE	STEERING WHEEL (Signal)
9	BLACK	AUDIO GND
10	BLACK	AUDIO GND

NOTE:

Both the 3.5mm jack plug and the BLUE wire are used for steering wheel remote. Please see page 4 for usage.

12v+ ACC OUTPUT (2)

PIN	COLOUR	FUNCTION
1	RED	12v+ ACC (OUT)
2	BLACK	GND

NOTE: 12v+ ACC (OUT) MAX CURRENT DRAW 1AMP (ideal for powering after market rear camera)

MAIN POWER HARNESS (3)*

PIN	COLOUR	FUNCTION
1	YELLOW	12v+ PERM
2	ORANGE	ILLUMINATION (OUT)
3	PURPLE/WHITE	REVERSE 12v+ (OUT)
4	BLUE	REMOTE IN
5	BLACK	GND
6	GREEN	Park Brake (OUT)
7	RED	12v+ ACC
8	PINK	SPEED PULSE (VSS)


*NOTE: Do NOT power anything aside from the radio with this harness! To use our ACC output, trigger a realy with the (red) wire from Harness(2).

CONNECTIONS

IMPORTANT NOTE:

After all the connections are made and the BENTLEY-HUR is powered up, remove the key ensuring all doors, boot and bonnet are closed. Also ensure the lights are off. Lock the car wait until the cluster goes to sleep, and allow an extra minute for the CAN to go to sleep. Now unlock as normal and the BENTLEY-HUR panel is now ready to use.

Make all connections from the BENTLEY-HUR to your aftermarket head-unit using the supplied harnesses.



NOTE 2:

Note: Due to the overwhelming amount of different radio models, there is no way to verify steering wheel control compatibility for any specific radio model, though most radio models are compatible.



Take trim remover and pry the speaker grill up and remove





Take hold of the trim panel and pull from the top and the bottom to remove





Lift trim panel and disconnect the black connector

Remove the 5 screws (t20 torx) as shown in photo





Carefully remove the Bentley head unit






Disconnect all connections to factory radio and remove from car.





Disconnect the Navigation CD drive in the glovebox.





Disconnect the CD Changer in the glovebox.






Remove the fuse for the phone module. Locate the fuse board in the driver side foot well






Remove the 5 amp fuse in location 28 for the phone module






Remove the navigation drive and the CD changer to make it easier to run the supplied GPS extension lead.





Connect the supplied GPS extension lead to the OEM GPS socket behind the CD navigation drive





Fibre optic connector

AM/FM radio connections



REMOVE AND DISCARD THE PLASTIC CABLE ASSEMBLY



Cable assembly



Remove the 4 x trim clip from original ZAB unit and clip into the supplied fasica






For the after market microphone and possible DAB antenna (GT / SPUR: N/A for US vehicles) remove the A pillar trim





Pry back trim next to door seal and use a feeder cable to get through to the glove box





Non-US vehicles only:

To remove the roof console you will require a right angled pick. Gently pry the OEM mic and alarm sensor out of the consol and remove the 2 x t20 torx screws behind, then pull down console.

Non-US vehicles only:

On GT / SPUR there are only certain locations where you can put the DAB antenna as the glass in the car is polarised and will affect reception. Top of the front screen is not polarised.










Once you have completed all the above, refit the trim panel and test to ensure all functions.

> NOTE: to adjust factory clock post install, the vehicle must be RUNNING.

If this vehicle was equipped with an OEM reverse camera and you'd like to retain it, locate the camera module (rear quarter near battery), disconnect the (gray) FAKRA connector, and extend this cable to the front with an RCA. The proper cables for an easy connection are available from NAV-TV, contact your sales representative for more information.



For full details on the operation of the BENTLEY-HUR fascia panel, please consult the USER GUIDE

Troubleshooting

- Q. Steering wheel controls don't work.
- A. Please check the dip switches are set correctly for your chosen head unit.
- Q. The BENTLEY-HUR panel is not functioning correctly after initial install.
- A. Please see "important note" on page 4.
- Q. No GPS reception on after market unit.
- A. Check connection of the GPS extension lead (supplied in the kit).
- Q. The LCD screen keeps turning off.
- A. Check to see if the LCD delay is turned on.
- Q. Unwanted noise at low level.
- A. Please check if the audio isolator has been fitted (certain units may need this).
- Q. The AM / FM is very poor.
- A. Check that the antenna amplifier is fitted correctly to the WHITE Fakra plug and there is 12v+ on the blue wire going to the antenna amplifier.
- Q. Where will I find the fuse for the BENTLEY-HUR in the car?
- A. Main fusebox under the driver side foot well FUSE 18 (10 amp)
- Q. Can I retain the OEM reverse camera?
- A. Yes, you will require an optional part BEN-HUR-OEMCAM (available from end Jan 2017)
- Q. Can I retain the OEM TV tuner?
- A. Yes, this can be controlled via the BENTLEY-HUR panel (available from end Jan 2017)

For technical support please call 1-866-477-3336 Please ensure you have followed the install manual before calling

NOTE:

After the BENTLEY-HUR panel has been fitted, and due to the fact that certain components have been disconnected, it will cause a fault code to be generated on the ODIS or VAGCOM diagnostic software systems. Please ignore fault codes relating to (J523) / (J401) / (J412)